

BELZONA FLOOR REPAIRS IN CIDER FACTORY

ID: 1575



PROBLEM

Lorry trailers park here and the stabilisers when lowered damage the floor area after 6-8 months.

APPLICATION SITUATION

Lorry park.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The repairing and protection of the floor in these localised areas with Belzona® 4131 resists both impact and abrasion thus extending the life of the floor area leading to reduced maintenance. The customer was very pleased with the results and this job has lead to several other applications being undertaken in the plant.

INDUSTRY

Buildings & Structures

LOCATION

Cider Manufacturer, UK

APPLICATION DATE

2009

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Preparation of damaged area
2. Application of Conditioner
3. Applying Belzona 4131
4. Completed Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®