

PROVEN BELZONA SUCCESS ON CONDENSATE TANK PROTECTION

ID: 1576



PROBLEM

Original competitor lining failed catastrophically.

APPLICATION SITUATION

Condensate tank, part of the Universities hot water system. Tank operates at 200°F, peaking up to 300°F under upset conditions.

APPLICATION METHOD

Application was carried out in accordance with modified Belzona Know-How System Leaflets TCC-3.

BELZONA FACTS

Original Belzona application was carried out in 2008. In August 2010 the application was inspected and only minor touch ups were required where underlying concrete had cracked.

INDUSTRY

Buildings & Structures

LOCATION

University, Southeast Wyoming

APPLICATION DATE

August 2008 & 2010

PRODUCTS

Belzona 1391 (Ceramic HT)

Belzona 1511 (Super HT Metal)

SUBSTRATE

Concrete

PHOTOS

1. Universities hot water plant
2. Original Belzona coating application
3. Touch-ups on tank walls
4. Touch-ups On tank floor

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

