

BELZONA PROVIDES LONG TERM SOLUTION IN COOL ROOMS

ID: 1578



3



4

PROBLEM

USDA inspectors made it clear that the leaks needed to be stopped. Floor needed to be repaired, coated and expansion joints sealed.

APPLICATION SITUATION

Second floor cooler (8500 ft²) was leaking onto the cooler on the lower floor.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & FPA-6.

BELZONA FACTS

After 14 years the floor was still water proof and without any leaks. Some scratches were present due to metal wheeled fork lifts but no water penetration. Small areas were touched up. Customer was very happy with longevity of the application.

INDUSTRY

General Industry

LOCATION

Poultry Plant, Virginia

APPLICATION DATE

1995

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 2221 (MP Fluid Elastomer)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Second Floor Cooler
2. After Original Application
3. Floor After 14 Years
4. Only Small Damage Present

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

