


EXTERNAL TANK CORROSION PROTECTION WITH BELZONA

ID: 1580



PROBLEM

Tank walls were suffering from external corrosion

APPLICATION SITUATION

Oil storage tank

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

10 years after the application, the inspection showed the Belzona product was in perfect condition. The Belzona application saved the customer an estimated US\$ 39,500 through reduced maintenance costs.

INDUSTRY

Chemical & Petrochemical

LOCATION

Fuel distribution company, Tamaulipas, Mexico

APPLICATION DATE

August 2000

PRODUCTS

Belzona 6111 (Liquid Anode) Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Carbon Steel

PHOTOS

Surface preparation Applying Belzona 6111 Application completed Tank ten years after application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

