

BELZONA REPAIRS UNDERWATER PIPE ON OFFSHORE PLATFORM

ID: 1582



PROBLEM

Sump pipe was cracked due to impact. It was required to seal the affected area under water.

APPLICATION SITUATION

Sump pipe on oil and gas platform

APPLICATION METHOD

Application was carried out using a modified version of Belzona Know-How System Leaflet VPF-11a. Surface was cleaned in accordance with ISO 8501-1 St2/3 using pneumatic sander. Prior to commencement of the application several plates were coated with Belzona® 5831 for future corrosion protection. Plates bonded in place by diver using Belzona® 1161. Clamps were used to hold plates in place during curing process.

BELZONA FACTS

Practical training was carried out with the divers prior to carrying out the actual application. Upon completion, inspection was carried out and a small leak was detected. The leak was repaired with the Belzona® 1161/5831 system. This repair is in perfect condition when last inspected in 2010.

INDUSTRY

Buildings & Structures

LOCATION

Oil and Gas Platform, Brazil

APPLICATION DATE

March 2008

PRODUCTS

Belzona 1161 (Super UW-Metal)
Belzona 5831 (ST-Barrier)

SUBSTRATE

Carbon Steel

PHOTOS

1. Adhesion test being carried out with plates coated with Belzona 5831 prior to application
2. Testing Belzona 1161 on edges of plate under immersed conditions
3. Application being carried out by divers under water

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

