

BELZONA CONTRIBUTES TO PUMP EFFICIENCY PROGRAMME IN STEEL PLANT

ID: 1583



PROBLEM

Damage due to erosion and corrosion caused high efficiency loss. The 12 selected pumps are 15 years old. But there are another 60 pumps 30-36 years old which have certainly higher efficiency loss as the tested ones.

APPLICATION SITUATION

Continuous casting plant of a steelmill has over 60 pumps used to provide cooling water to casting rolls, burner injectors of blast furnace and other different areas. 12 pumps were identified for coating and efficiency monitoring.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-10.

BELZONA FACTS

Steelmill installed new digital control system for the proper monitoring of power consumption, volume and water pressure. Before and after result: -10-12% less power consumption +12,5% more pressure +12,5% higher head. The energy saving in a year covers the cost of the coating.

INDUSTRY

General Industry

LOCATION

Steel plant, Hungary

APPLICATION DATE

2010

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1341 (Supermetalglide)

SUBSTRATE

Steel

PHOTOS

1. Pump surface before coating
2. Grit blasted impeller
3. Coated parts
4. Coated housing

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

