

BELZONA RESTORES HYGIENE LEVELS IN SWEET/CANDY MANUFACTURER

ID: 1585



PROBLEM

New Kitchen was being installed and required repairs to walls and a coating to be applied to ensure hygiene levels were met.

APPLICATION SITUATION

Concrete Repair and coating required to internal walls.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets WPA-2 & 4. The damaged areas were repaired using Belzona 4141 to ensure smooth surface for application of the Belzona 5111 System.

BELZONA FACTS

Initially 1/3 of the kitchen areas were refurbished with the Belzona System. Since then the customer has been so pleased with the results that they plan to complete the rest of the kitchen areas. 12 years later, the coating is still in great condition proving a highly decorative, non-toxic wall surface which is easy to clean.

INDUSTRY

General Industry

LOCATION

Sweet/Candy Manufacturer, West Yorkshire, UK

APPLICATION DATE

June 2008

PRODUCTS

Belzona 4141 (Magma Build) Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Concrete

PHOTOS

1. Kitchen area to be coated
2. Belzona 5911 (Ceramic Conditioner) being applied
3. Completed wall coating
4. Wall coating revisited 12 years later

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

