

BELZONA UPGRADE TO FLOOR IN CHOCOLATE FACTORY

ID: 1588



PROBLEM

The existing coating had begun to deteriorate and sections of the main walk area had been removed exposing the concrete substrate beneath. This was not only unsightly; it also represented a health risk as staff were unable to clean the floor area adequately as food particles become trapped in the surface. The area also presented a considerable slip risk.

APPLICATION SITUATION

Floor in canteen wash area.

APPLICATION METHOD

The remainder of the original floor coating was uplifted and the whole concrete floor area Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3.

BELZONA FACTS

The clients requirements and expectations have been met in full and they are very pleased with the results. the floor provides a hygienic surface that cannot harbour bacteria and also provides a slip resistant surface for the staff.

INDUSTRY

General Industry

LOCATION

Chocolate manufacturer, Derbyshire, UK

APPLICATION DATE

December 2009

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Floor Areas to be Repaired
2. Floor Areas to be Repaired
3. Completed Floor Application
4. Completed Floor Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

