


BELZONA UPGRADES FLOOR IN FOOD PREPARATION AREA

ID: 1596



PROBLEM

The floor was slippery creating a health and safety issue. In addition the concrete was being damaged around drains.

APPLICATION SITUATION

Floor in food preparation area.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating before applying the 2 coat Belzona® 5231 system by roller.

BELZONA FACTS

The school chose the Belzona solution for their floor problems as they wanted a seamless, hard-wearing and long lasting coating. They had a maximum of 4 days to complete the repair and Belzona were the only company able to accommodate this.

INDUSTRY

Buildings & Structures

LOCATION

School, UK

APPLICATION DATE

October 2010

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Floor Problem Area
2. Floor Problem Area
3. Completed Floor Application
4. Completed Floor Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

