

BELZONA RESTORES HYGEINE IN BOTTLING ROOM

ID: 1605



PROBLEM

There were several cracked and broken tiles. This created a potential hygiene problem and required rectifying to remove traps for bacteria and to aid cleaning.

APPLICATION SITUATION

Tiled floor in bottling room.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & 3. Belzona® 4131 was used to replace loose tiles and create a uniform surface prior to application of the Belzona® 5231.

BELZONA FACTS

The Belzona System creates a level, seamless surface that is hygienic in this critical area. The low VOC, low odour of the system was a further benefit in this bottling plant.

INDUSTRY

Buildings & Structures

LOCATION

Bottled Water Manufacturer, Perthshire, UK

APPLICATION DATE

September 2010

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 5231 (S G Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Damaged tiles being repaired with Belzona 4131
2. Floor levelled with Belzona 4131
3. Light grey Belzona 5231 being applied
4. Completed floor coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

