

# BELZONA REFURBISHMENT MAKES FIRE ESCAPE SAFE

ID: 1606



## PROBLEM

Regular foot traffic and weathering caused the steps of this fire escape to become damaged and worn and had made it a potential slip hazard.

## APPLICATION SITUATION

Fire escape stairs

## APPLICATION METHOD

Application was carried out in accordance with a modified Belzona Know-How System Leaflet FPA-8. Belzona® 4411 (Granogrip) was applied to the steps with aggregate incorporated in grey and yellow. Belzona® 5111/6111 system applied to the hand rails. Belzona® 1111 was used to smooth out corroded steelwork.

## BELZONA FACTS

This solution was chosen as it is a long life and cost effective repair. The customer was extremely pleased with the aesthetic appearance of the application. The Belzona Grip system provides both positive grip and improved visibility to step nosings.

## INDUSTRY

Buildings & Structures

## LOCATION

Police Station, UK

## APPLICATION DATE

November 2010

## PRODUCTS

Belzona 4411 (Granogrip)  
Belzona 5111 (Ceramic Cladding)  
Belzona 6111 (Liquid Anode)

## SUBSTRATE

Steel

## PHOTOS

1. Original condition of the entrance steps
2. Original condition of the entrance steps
3. The finished application
4. The finished application

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © 1952-2026 Belzona International Limited.

  
**BELZONA®**