


ROUTINE BELZONA TANK BASE SEALING APPLICATION

ID: 1616



PROBLEM

Bitumen sealant had failed to seal beneath the tank base allowing water penetration.

APPLICATION SITUATION

Fuel storage tanks

APPLICATION METHOD

Application was carried out in accordance with Belzona® Know-How System Leaflets GSS-3.

BELZONA FACTS

The flexibility of the Tank Base Sealing System is ideally suited to operation in this hot tropical climate. This is one of more than 50 such tanks now protected with the Belzona Tank Base Sealing System.

INDUSTRY

Buildings & Structures

LOCATION

Refinery, Thailand

APPLICATION DATE

2002- ongoing

PRODUCTS

Belzona 3111 (Flexible Membrane System)

SUBSTRATE

Steel, concrete

PHOTOS

1. General view of the tank
2. Deteriorated bitumen being removed
3. Substrate conditioned
4. Belzona 3111 being applied to complete the system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

