

PRISON MUSEUM STEPS MADE SAFE WITH BELZONA

ID: 164



PROBLEM

Severe weathering damage caused an unsafe condition for tourists visiting the site. Exposed rebar was causing the damage to accelerate.

APPLICATION SITUATION

Stairway into the prison museum

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet FPA-1.

BELZONA FACTS

The application was carried out with Belzona® 4111 (Magma Quartz) molded in place with formers. Today, Belzona® 4141 (Magma Build) would make for a faster, easier repair. The hazardous conditions were eliminated and the repair is still in service as of March, 1996.

INDUSTRY

General Industry

LOCATION

Prison Museum in the Bay Area of California

APPLICATION DATE

June 1984

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Steel reinforced concrete

PHOTOS

1. Sign at entrance
2. Damage on underside of stairs, note exposed rebar on landing
3. Completed repair to stair
4. Repairs were also made to chipped concrete on stair tops

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.