

BELZONA REVISITS LEAKING PIPE

ID: 1640



PROBLEM

Leaking pipe was affecting efficiency of the cooling system. Back pressure meant repair had to be carried out live and to a very tight schedule. Adjacent section of pipe had previously been repaired with Belzona.

APPLICATION SITUATION

Cooling water pipework

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a. After temporarily stemming leak with Belzona® 1291, Belzona® 1221 was applied to give additional strength before grit blasting and applying a Belzona® 1111 wrap. Belzona® 1341 was applied over the top to provide corrosion protection to exposed section of pipe.

BELZONA FACTS

Just 2 hours after completing the repair, the full pressure was restored. This repair has now been in service 3 years with the earlier repair now 7 years in service.

INDUSTRY

Buildings & Structures

LOCATION

Power Station, Wales

APPLICATION DATE

February 2008

PRODUCTS

Belzona 1111 (Super Metal) Belzona 1221 (Super E Metal) Belzona 1291 (ES Metal)

SUBSTRATE

Steel

PHOTOS

The leak Belzona 1111 wrap completed
Completed application protected with
Belzona 1341 Note earlier repair
immediately below latest repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

