

BELZONA OVERCOMES PROBLEM OF LEAD THEFT

ID: 1643



PROBLEM

This school had recently suffered from theft of the lead from their roof. The damage was so extensive that if not addressed, it would lead to structural defects resulting in a potentially disruptive high cost maintenance repair.

APPLICATION SITUATION

Window canopies on roof of a local school

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-2. Roof was felted prior to sealing with fully reinforced Belzona® 3111 system.

BELZONA FACTS

The repairs were completed in less than one week. Revisiting the application in 2010, the school has not experienced any further problems, and the repair is still in excellent condition.

INDUSTRY

Buildings & Structures

LOCATION

Local School, UK

APPLICATION DATE

2008

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Felt and slate

PHOTOS

1. Window before application
2. General view of the roof
3. Application completed
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

