

BELZONA REPAIRS ROOF AT PRESTIGIOUS UNIVERSITY

ID: 1646



PROBLEM

Strict requirements needed to be adhered to when repairing this roof. Application had to be carried out with library in full use by students.

APPLICATION SITUATION

The mineral felt roof and gutters were in poor condition with various areas leaking directly into the reading room below where many historic books are stored and read daily by students.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, 6 & 8.

BELZONA FACTS

The University had experienced problems before with students complaining about the smell and feeling ill due to competitors solvent-based roofing products being used on other University buildings. Belzona® 3111 fully reinforced system was applied without disruption to the daily use of the library reading rooms below.

INDUSTRY

Buildings & Structures

LOCATION

University Library, UK

APPLICATION DATE

Summer 2010

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Mineral felt with chippings

PHOTOS

1. Damaged gutter prior to the application
2. Gutter coated with Belzona 3111
3. Leaking roof area
4. Roof coated with Belzona 3111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

