


BELZONA SEALS ROOFTOP EXPANSION JOINTS

ID: 1648



PROBLEM

Pond had been drained for refurbishment and concern was expressed over the waterproofing of the expansion joints.

APPLICATION SITUATION

Pond on roof of university

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & RPA-1. After cleaning and drying, all loose concrete was removed and repaired using Belzona® 4111 followed by two coats of reinforced Belzona® 3121 to bridge the joints.

BELZONA FACTS

The repairs were carried out in the depths of winter allowing the project to be completed ahead of schedule.

INDUSTRY

Buildings & Structures

LOCATION

University, Leeds, UK

APPLICATION DATE

December 2010

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 3121 (MR 7)

SUBSTRATE

Concrete

PHOTOS

1. Roof showing signs of damage
2. Close up of the damage
3. Application in progress
4. The application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

