

BELZONA REPAIRS LEAKING SCHOOL ROOF

ID: 1649



PROBLEM

The roof was leaking at the joints, seams and gutters.

APPLICATION SITUATION

Low pitch zinc sheet roof at school.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1 & 6.

BELZONA FACTS

On this roof the College required coloured demarcation of no walk zones (light grey) and walkways (dark grey) across the roof for the maintenance teams to access the plant and clean gutters safely.

INDUSTRY

General Industry

LOCATION

Public school, UK

APPLICATION DATE

July 2009

PRODUCTS

Belzona 3131 (WG Membrane)

SUBSTRATE

Zinc

PHOTOS

1. Prior to application
2. Roof part 1, the completed application
3. Roof part 2 before application
4. Roof part 2 completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

