

BELZONA REPAIRS SUN DAMAGE ON ROOF

ID: 168



PROBLEM

Leaks at seams, bituminous coating is damaged

APPLICATION SITUATION

Extraction Ducting

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet RPA-1.

BELZONA FACTS

The tar was severely damaged due to the effects of the sun; further application of the bituminous coating would have also failed. Belzona® 3111 (Flexible Membrane) solved the problem on the roof.

INDUSTRY

General Industry

LOCATION

Railway Engineering Workshops in Northern England

APPLICATION DATE

June 1996

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete treated with bitumen

PHOTOS

1. Failed bituminous coating
2. Seam areas addressed
3. Ducting completely protected and sealed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

