

BELZONA REPAIRS COLOUR MATCH SPALLED LINTELS

ID: 1681



PROBLEM

Spalled concrete due to rebar corrosion.

APPLICATION SITUATION

Concrete lintels.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet WPA-4. Belzona® 4141 was colour matched to existing concrete using Iron Oxide pigments.

BELZONA FACTS

Repair was carried out quickly without need for scaffolding or permanent shuttering. Ability to colour match the repair ensured aesthetic acceptability.

INDUSTRY

Buildings & Structures

LOCATION

Local Education Authority, UK

APPLICATION DATE

September 2009

PRODUCTS

Belzona 4141 (Magma Build)

SUBSTRATE

Concrete

PHOTOS

1. Spalled concrete.
2. Application in process using straight edge to form neat corner.
3. Completing the application.
4. Completed application. Note excellent colour match.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

