

BELZONA REFURBISHES THE FLOORS

ID: 169



PROBLEM

Water was trapped under the tile, causing the tile to break up and providing a haven for bacteria and mold. Pushing the carts over rough, broken, and missing tile posed a serious safety hazard as well.

APPLICATION SITUATION

Wash area floor for aircraft food service carts

APPLICATION METHOD

Old concrete was removed and 1 1/2" voids were left in several areas. Belzona® 4131 (Magma Screed) was applied over the areas where the minimum depth was 3/8". The application was carried out in accordance with Belzona Know-How Leaflet FPA-1.

BELZONA FACTS

The application covered a 72 square foot area and took only two hours to complete. The wash area is now a safer and cleaner place to work.

INDUSTRY

General Industry

LOCATION

Airport Food Service in Missouri

APPLICATION DATE

February 1996

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Removing old tile, dirt and concrete
2. Beginning application of Belzona 4131 (Magma Screed)
3. Job almost completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

