

BELZONA KEEPS THE BEER BREWING

ID: 170



PROBLEM

A chemical containment area was leaking chemicals around the perimeter of the area.

APPLICATION SITUATION

Bromine chemical containment area at brewery

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet TCC-15.

BELZONA FACTS

Costly environmental regulatory fines were averted by using Belzona. The chemicals were contained and the dike was protected.

INDUSTRY

General Industry

LOCATION

Brewery in Texas

APPLICATION DATE

March 1995

PRODUCTS

Belzona 4311 (Magma CR-1)

SUBSTRATE

Concrete

PHOTOS

1. Work begins early in the day.
2. Following application of the Belzona 4911 primer coat, the first coat of Belzona 4311, red, was applied. Application of the second gray coat is in progress.
3. The finished Belzona 4311 protective coating is now ready for service.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

