

# BELZONA ATTENTION ON THE ROOF

ID: 172



## PROBLEM

This building had been renovated, severe leaks were destroying new ceiling tiles and wallpaper. Flashings were pulled away from the wall and water gushed in.

## APPLICATION SITUATION

Roof

## APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet RPA-8.

## BELZONA FACTS

240 linear feet by 2 feet wide was coated in five hours. One hour later, a heavy rain blew in, there were no leaks and no damage to the Belzona® 3111 (Flexible Membrane). The roof is now watertight.

## INDUSTRY

General Industry

## LOCATION

U.S. Air Force Base in Illinois, USA

## APPLICATION DATE

July 1995

## PRODUCTS

Belzona 3111 (Flexible Membrane)  
Belzona 9311 (Membrane Reinforcing Sheet)

## SUBSTRATE

Conventional four ply build up roof and brick

## PHOTOS

1. Belzona 9311 (Membrane Reinforcing sheet) is pre-wetted prior to application.
2. Second coat of Belzona 3111 (Flexible Membrane) over first.
3. The finishing touches.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

