

BELZONA CONTAINMENT DIKE SEALED

ID: 174



PROBLEM

Previous coating had failed causing minor damage to the dike curb and pump pads.

APPLICATION SITUATION

Sodium bicarbonate chemical tank containment area at brewery.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflet TCC-15.

BELZONA FACTS

Previous vinyl ester coating had failed. Belzona® 4151 (Magma Quartz Resins) solved the problem. Sealing this containment area prevented possible leakage and shutdown of this critical operation.

INDUSTRY

General Industry

LOCATION

Beer Manufacturer in Texas, U.S.A.

APPLICATION DATE

February 1995

PRODUCTS

Belzona 4151 (Magma Quartz Resins)

SUBSTRATE

Concrete

PHOTOS

1. The containment area.
2. Application of Belzona 4151 (Magma Quartz Resins) nearing completion.
3. The containment area now protected with Belzona.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

