

BELZONA LEAD CHAPEL ROOF

ID: 175



PROBLEM

Deteriorating lead roof required long-term protection.

APPLICATION SITUATION

Chapel roof at major university

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How Leaflet RPA-1.

BELZONA FACTS

This 70-year-old roof had experienced deterioration over the years due to atmospheric conditions. The university was considering replacement, however, due to the prestigious work that was done on the lead roofs of the House of Lords in the U.K., Belzona was chosen for this project and extended the life of the lead roof.

INDUSTRY

General Industry

LOCATION

Prestigious Ivy League University in the Northeast, U.S.A.

APPLICATION DATE

Summer 1996

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (GSC Surface Conditioner)
Belzona 9311 (Membrane Reinforcing Sheet)

SUBSTRATE

Lead

PHOTOS

1. Belzona 3111 (Flexible Membrane) applied to the right, Belzona 3921 (GSC Surface Conditioner) being applied at left, uncoated section lower left.
2. Work continues at the apex.
3. Front view of the chapel, lead roof protected.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

