

BELZONA STAIRWELL MADE SAFE

ID: 176



PROBLEM

Stairs were spalled and deteriorated and required a non-slip safety surface.

APPLICATION SITUATION

Stairwell for Navy V.I.P. entrance

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflets FPA-1 and FPA-8.

BELZONA FACTS

The application of several Belzona products provided a safe and aesthetically pleasing stairwell, suitable for Navy V.I.P.'s.

INDUSTRY

General Industry

LOCATION

U.S. Naval Base in South Mississippi, U.S.A.

APPLICATION DATE

December 1995

PRODUCTS

Belzona 1341 (Supermetalgilde)
Belzona 4131 (Magma Screed)
Belzona 4911 (Magma TX Conditioner)
Belzona 5111 (Ceramic Cladding)
Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

PHOTOS

1. Steps resurfaced with Belzona 4131 (Magma Screed).
2. Belzona 5111 (Ceramic Cladding) applied for aesthetic reasons, and Belzona 1341 (Supermetalgilde) grip system applied primarily for safety reasons.
3. At the foot of the stairs, the non-slip Navy logo was created with a stencil.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

