


BELZONA DOES FLOORS

ID: 186



PROBLEM

Extreme erosion surrounding drains due to acidic water discharge

APPLICATION SITUATION

Chemical containment floor drainage area

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflet TCC-9.

BELZONA FACTS

Concrete would not hold up to the conditions. To remove the tanks and install a new floor would cost \$60,000 and require 2-3 weeks downtime. Preparation took 8 hours and the application of product took 8 hours. The customer saved \$50,000 by using Belzona.

INDUSTRY

General Industry

LOCATION

Beverage Canning Company in Mississippi, U.S.A.

APPLICATION DATE

January 1996

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Application commences, note the erosion of the concrete drain area.
2. Application proceeds.
3. Finished application, concrete protected and proper drainage restored.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

