

BELZONA HEATING PIPE FITTINGS ABOARD SUPERTANKER

ID: 190



PROBLEM

Pipe fittings continued to leak.

APPLICATION SITUATION

Ship was being refitted and repaired so a new type of fuel additive could be carried. Heater lines keep the cargo warm and fluid.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflet VPF-11a.

BELZONA FACTS

Millions of dollars in lost revenue were at stake. Other options such as silver solder and expensive fittings from Europe. Belzona solved the emergency quickly and cost effectively, allowing the ship to sail on time.

INDUSTRY

Marine

LOCATION

A 600-foot supertanker barge at Tampa Bay, Florida, U.S.A.

APPLICATION DATE

January 1997

PRODUCTS

Belzona 1211 (E-Metal)

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Following surface preparation, a collar was used
2. Application of product
3. Pipe fittings and sea dogs are happy with the repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

