

LONG TERM ROOF REPAIR BY BELZONA

ID: 1904



PROBLEM

Severely deteriorated asbestos roof tiles were no longer providing weather protection.

APPLICATION SITUATION

Asbestos tiled roof of an old villa.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

BELZONA FACTS

After 10 years in service, the application was reviewed and still found to be in an excellent condition. Due to the reliable performance of Belzona, the customer opted again for Belzona® 3111 to refurbish the roof after 23 years service.

INDUSTRY

Buildings & Structures

LOCATION

Old private villa, Italy

APPLICATION DATE

1985 and 2008

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Asbestos

PHOTOS

1. Damaged roof in 1985
2. Roof application after 10 years in service
3. Close-up after 10 years in service
4. Refurbishment in 2008 again with Belzona 3111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

