


BELZONA COATING FOR A REFINERY KNOCK-OUT DRUM

ID: 1913



PROBLEM

The replacement of the drum was a major part of the refinery shut-down and a corrosion resistant lining was required to maximise the vessels useful service life.

APPLICATION SITUATION

Low pressure flare knock-out drum measuring approximately 12 metres in length and 5 metres in diameter.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. Belzona® 1391 for stripe coating of all welds and nozzles prior to the application of Belzona® 1521 using airless spray equipment.

BELZONA FACTS

Belzona coatings were chosen for their ability to provide corrosion protection at the elevated temperatures and pressures involved. In particular resistance to rapid decompression was essential.

INDUSTRY

Chemical & Petrochemical

LOCATION

Refinery, UK

APPLICATION DATE

January 2007

PRODUCTS

Belzona 1521 (HTS1)

SUBSTRATE

Steel

PHOTOS

1. The vessel in the workshop
2. Smoothing the welds by grinding
3. Mixing the material
4. Spraying underway

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

