

# BELZONA 4111 MAINTAINS SAFE FACTORY ENVIRONMENT

ID: 202



## PROBLEM

Leakage of cutting oils, lubricants and printing inks from the machinery create a serious slip and skid hazard.

## APPLICATION SITUATION

Pedestrian and fork lift access areas around production machinery.

## APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-9.

## BELZONA FACTS

Three inch plastic half pipes were used to form the Belzona® 4111 thereby creating a bund or containment area around each machine. The Belzona application has withstood heavy duty use and is resistant to the various oils and chemicals in use. The application also has helped to satisfy hygiene inspectors previously concerned with floor contamination.

## INDUSTRY

General Industry

## LOCATION

Manufacturing plant

## APPLICATION DATE

1978 & 1998

## PRODUCTS

Belzona 4111 (Magma-Quartz)

## SUBSTRATE

Concrete

## PHOTOS

1. Former being positioned
2. General view of machines with formed bunds
3. Close-up of the formed bund

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

