

BELZONA 4131 REPAIRS TO SPALLED CONCRETE

ID: 203



PROBLEM

Extensive spalling had made using the hand-rail unsafe.

APPLICATION SITUATION

Canopy over a busy shopping area

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

BELZONA FACTS

When work initially started damage was found to be more extensive than originally thought. Old railings were replaced. Rapid repairs with Belzona® 4131 ensured minimum disruption.

INDUSTRY

General Industry

LOCATION

Local Authority

APPLICATION DATE

1999

PRODUCTS

Belzona 4131 (Magma-Screed)

SUBSTRATE

Concrete and stainless steel

PHOTOS

1. General view of the site with specially boarded up Acrows insisted on by safety officials
2. The degree of concrete damage clearly evident
3. Rebuilding complete and gutter re-instated

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

