

BELZONA SEALS SWIMMING POOL LEAKS

ID: 205



PROBLEM

The original Silicone sealant had deteriorated allowing large water losses.

APPLICATION SITUATION

Expansion joints in swimming pool

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

Water losses were estimated to cost \$3,300 per month (replacement, heating and treatment). This type of application has been carried out for 14 years with great success. The Belzona® 4111 is tinted blue, grey and beige to match the pool design.

INDUSTRY

General Industry

LOCATION

Municipality

APPLICATION DATE

August 1999

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. General view of the pool
2. Joint nosings rebuilt with tinted belzona 4111
3. Joint being masked prior to sealing with Belzona 2211

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

