


BELZONA REFURBISHES SCRUBBER RUBBER

ID: 207



PROBLEM

Once the rubber was gone, the exposed carbon steel would only last one week.

APPLICATION SITUATION

Rubber lining on a scrubber unit was worn away leaving carbon steel exposed.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflets SHM-8 and SHM-9.

BELZONA FACTS

By utilizing the Belzona solution, wear on the carbon steel pipe was eliminated, thereby reducing maintenance costs and extending the life of the equipment.

INDUSTRY

Power

LOCATION

TVA Powerplant (Tennessee Valley Authority- U.S.A.)

APPLICATION DATE

July 2000

PRODUCTS

Belzona 1812

SUBSTRATE

Carbon steel pipe

PHOTOS

1. Application begins
2. Application continues
3. Close-up view at a repaired area

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

