


BELZONA REDUCES COST OF EXPANSION JOINT REFURBISHMENT

ID: 2085



PROBLEM

Deterioration of expansion joints were a constant problem. This facility would budget annually for the replacement of expansion joint material. This repetitive repair and refurbishment work was creating a constant drain on the annual maintenance budget.

APPLICATION SITUATION

The original expansion joint material had failed and no longer provided a seal between the various slabs of concrete.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

After the installation of the Belzona Elastomer joints, annual refurbishment of the expansion joints was eliminated. These joints are now 7 years old and still providing protection

INDUSTRY

General Industry

LOCATION

Public Recreation Facility, BC, Canada

APPLICATION DATE

March 1997

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete and ceramic tile

PHOTOS

1. General view of deteriorated expansion joint
2. Application in progress
3. View of a completed expansion joint section

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

