

BELZONA SEALS ACCESS RAMP LEAKS

ID: 2086



PROBLEM

The caulking between the walls and ramp base needed to be replaced on a regular basis to prevent water from entering into the area below.

APPLICATION SITUATION

Water was entering the storage and equipment areas below.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet RPA-1.

BELZONA FACTS

Belzona® 3111 Flexible Membrane was used to create a flexible flashing between the wall and floor eliminating the previous repetitive maintenance with sealants.

INDUSTRY

Buildings & Structures

LOCATION

Recreation Center, BC, Canada

APPLICATION DATE

September 2002

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete

PHOTOS

1. View of joint to be sealed
2. Application of 1st coat of Belzona 3111 incorporating Reinforcement Sheet
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

