

BOILING WATER: NO PROBLEM FOR BELZONA 4181

ID: 210



PROBLEM

Boiling water had broken down an existing epoxy coating and the underlying concrete floor it was supposed to protect.

APPLICATION SITUATION

Hospital kitchen floor

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & FPA-3.

BELZONA FACTS

The area was tented to protect the surrounding area and the remaining coating was removed. Belzona® 4181 was able to withstand the boiling water and is now being considered for other application areas.

INDUSTRY

General Industry

LOCATION

Hospital

APPLICATION DATE

July 2000

PRODUCTS

Belzona 4181

SUBSTRATE

Concrete

PHOTOS

1. General view of floor problem area
2. Close-up of damaged area around drainage channel
3. Belzona 4181 application underway
4. The finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.