

BELZONA 3111 PROVEN PERFORMANCE

ID: 215



PROBLEM

Severe water penetration, particularly through joints, seams, glazing units and gutters.

APPLICATION SITUATION

Roof areas over offices and workshops.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-3 and RPA-6.

BELZONA FACTS

Belzona was chosen over other materials as previous repairs with competitive materials on the site had underperformed. Belzona system lived up to expectations and was in excellent condition when inspected in 1997.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical plant in the United Kingdom

APPLICATION DATE

1986 and 1988

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Asbestos and asphalt

PHOTOS

1. Work underway on the workshop roof
2. Horizontal area of office roof undergoing treatment
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

