

BELZONA RAPID REPAIR TO VIADUCT RAILING SUPPORT

ID: 2161



PROBLEM

The concrete base for railings support pillars was cracked and spalled.

APPLICATION SITUATION

Pedestrian pavement beneath viaduct.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

BELZONA FACTS

The application was achieved in 2 hours and without the need for any formwork. This application is still in excellent condition when inspected in 2011.

INDUSTRY

General Industry

LOCATION

Town council, Canada

APPLICATION DATE

May 2003

PRODUCTS

Belzona 4141 (Magma-Build)

SUBSTRATE

Concrete and steel

PHOTOS

Concrete condition before the application The concrete is coated with Belzona 4911 Conditioner Belzona 4141 application completed quickly and easily without the use of formwork

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.