

BELZONA AVOIDS SLIP PROBLEMS

ID: 2162



PROBLEM

The belt was slipping on the drive rollers due to water from the poor seasonal weather.

APPLICATION SITUATION

Drive drums from conveyor system

APPLICATION METHOD

Application carried out according to Belzona Know-How System Leaflet SHM-12.

BELZONA FACTS

Two drive rollers were treated and performed perfectly for a full year without any evidence of slipping. The Belzona Grip System has performed better than rubber and other lagging systems previously used.

INDUSTRY

Mining & Quarrying

LOCATION

Mining company, Canada

APPLICATION DATE

August 2007

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

Belzona 9221 (Surefoot Aggregate)

SUBSTRATE

Steel

PHOTOS

1. Steel roller
2. After preparation, coating with Belzona 1321
3. Finished roller

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

