

# BELZONA PROTECTS HYDROELECTRIC TURBINE RUNNER

ID: 218



## PROBLEM

Over 40 years of service led to cavitation and corrosion.

## APPLICATION SITUATION

Francis turbine runner

## APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets CEP-3 and CEP-5.

## BELZONA FACTS

Conventional weld repairs would have been cost prohibitive. In addition, Belzona repairs do not create heat stress, an increase in efficiency is expected. The turbine does not operate full time. In summer there is often only enough water for operation one day per week.

## INDUSTRY

Power

## LOCATION

Hydroelectric power plant in Scotland

## APPLICATION DATE

November 2000

## PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalglide)

## SUBSTRATE

Phosphor Bronze

## PHOTOS

1. The runner prior to application
2. Application underway with second coat of Belzona 1341 being applied
3. The completed application with the smoothness of Belzona 1341 clearly evident

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

