

BELZONA KEEPS WORN HOSE WORKING

ID: 220



PROBLEM

The uploading cement hose had worn through to the reinforcement wire.

APPLICATION SITUATION

Worn rubber hose

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

A quick reliable repair was required and other than replacement, Belzona was the only option.

INDUSTRY

General Industry

LOCATION

Shipping company in Canada

APPLICATION DATE

November 2000

PRODUCTS

Belzona 2311 (SR-Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Overview of damaged area
2. Loose pieces have been removed
3. The conditioner, reinforcement sheet and Belzona 2311 (SR-Elastomer) have been used to fill area
4. The finished repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

