



BELZONA REPAIRS SUCTION DRUM EXIT

ID: 228



PROBLEM

Severe corrosion produced by water and clay.

APPLICATION SITUATION

Exit section of a paper suction drum.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflets FBC-5 and -7.

BELZONA FACTS

The repair was done in two days for under \$6,700. The conventional approach would mean that the equipment would be sent outside the country and cost over \$30,000 for transportation and repair.

INDUSTRY

Pulp & Paper

LOCATION

Papermill in Quebec, Canada

APPLICATION DATE

September 2000

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel and nickel alloy

PHOTOS

1. The equipment prior to repair
2. The surface has been prepared
3. Perforation repair using Belzona 1311 (Ceramic R-Metal) and perforated metal sheet
4. Equipment is ready to be put back into service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

