

BELZONA REFURBISHES STEPS AT HISTORIC COLLEGE

ID: 2299



PROBLEM

The steps had worn badly over the last few hundred years. The main contractor had to find a product that they could apply in the evening shift so the staircases could be re-opened ready for the busy work force in the morning to carry on with the rest of the project. The contractor only had six weeks to complete the total College refurbishment.

APPLICATION SITUATION

The College was undergoing a complete refurbishment of the student accommodation area. Part of the work was to rebuild the two staircases at both ends of the building.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The contractor chose Belzona as he had previous experience with the products and knew he could have the stairs repaired and back in service in the short time available. The excellent wear characteristics will also ensure steps do not require repair in the foreseeable future.

INDUSTRY

Buildings & Structures

LOCATION

College, Oxford, UK

APPLICATION DATE

September 2011

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Stone

PHOTOS

1. Worn steps before the application
2. Steps during the preparation
3. Steps rebuilt back to profile
4. Completed application ready for the overlay of carpet

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

