

BELZONA LEVELS LOADING QUAY

ID: 2365



PROBLEM

The uneven surface (measuring 1 inch) between two concrete sections was causing impact problems to forklift trucks driving through. The impact caused pain to the personnel operating these trucks, as well as jeopardising the balance and security of the loads.

APPLICATION SITUATION

Loading quay

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

A less costly alternative repair had lasted only 6 month (picture 1). Belzona 4111 is still intact after 1 year in service, due to its excellent bond strength, impact resistance and compressive strength.

INDUSTRY

Buildings & Structures

LOCATION

Animal feed manufacturer, Canada

APPLICATION DATE

November 2006

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. The failed previous alternative repair
2. Surface preparation
3. Completed application
4. Application after 1 year

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

