

BELZONA SEALS EXPANSION JOINTS

ID: 238



PROBLEM

Contact with chemicals and sugar juice deteriorate expansion joint sealing material.

APPLICATION SITUATION

Expansion joints in sugar processing facility.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflets FPA-6.

BELZONA FACTS

The use of an appropriate expansion joint sealant prevents maintenance shutdowns and conserves the integrity of floor areas.

INDUSTRY

Sugar

LOCATION

Sugar Beet mill in Minnesota, U.S.A.

APPLICATION DATE

1991

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. Severely damaged expansion joints
2. Cleaned and prepared expansion joint before the use of Belzona 2221
3. Successfully sealed expansion joints

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

