

BELZONA REPAIRS COLLEGE STEPS

ID: 2451



PROBLEM

Heavy foot traffic and weathering caused the steps at this college to become damaged and worn.

APPLICATION SITUATION

Damaged steps at public college

APPLICATION METHOD

Application was carried out in accordance with the Belzona Know-How System Leaflets FPA-1 and FPA-8

BELZONA FACTS

Belzona products were required in order to give a fast, long-lasting and cost-effective repair. The ability to bond to and build up old concrete meant that the steps did not have to be completely removed and rebuilt. Belzona® 4411 was applied to the step nosings to provide a safety grip system and to ensure there was a contrast in colour, in order to meet the current DDA regulations regarding partially sighted people.

INDUSTRY

Buildings & Structures

LOCATION

College, East Midlands, UK

APPLICATION DATE

August 2011

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. General view of the damaged steps
2. First application of Belzona 4131
3. Application being carried out
4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

