

BELZONA STOPS FLOOR DRAIN LEAKS

ID: 2458



PROBLEM

Leakage from the floor drains was problem from the start. Connection between steel and tiles was faulty. Result was the leakage to the next floor.

APPLICATION SITUATION

Drain in kitchen floor.

APPLICATION METHOD

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1

BELZONA FACTS

Customer had tried several alternatives to repair the drain but none worked. Repair with Belzona® 4111 ensured necessary water tightness due to excellent adhesion to different substrates and non-shrink properties.

INDUSTRY

General Industry

LOCATION

Machinery manufacturer, Slovakia

APPLICATION DATE

2008

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

stainless steel, concrete, ceramic tiles

PHOTOS

1. Situation before repair
2. Situation at the floor below
3. Surface preparation being carried out
4. Belzona 4111 in place creating a watertight seal

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

