

BELZONA SECURES DANGEROUS WALKING AREAS

ID: 2476



PROBLEM

The stairs and walkways, located outside, were very slippery when wet.

APPLICATION SITUATION

Stairs and walkway areas accessing a municipal building.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4411 was applied on stair treads and floor, using stencils to create non slip patterns on each tile.

BELZONA FACTS

This solution created a durable non-slip surface on the tiled floor whilst at same time presenting an aesthetically acceptable appearance.

INDUSTRY

Buildings & Structures

LOCATION

Municipal building, France

APPLICATION DATE

2004

PRODUCTS

Belzona 4411 (Granogrip)

SUBSTRATE

Tiles

PHOTOS

1. The external staircase
2. Completed application on the stairs
3. Application in progress on the walkways using stencil to create pattern
4. Completed application on the walkway

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

