

BELZONA SECURES THE TOWN HALL STEPS

ID: 2477



PROBLEM

The steps were damaged through impact and were extremely slippery when wet.

APPLICATION SITUATION

Entrance steps to the town hall.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-8 & FPA-1. The steps were rebuilt with Belzona® 4111. A 3cm wide strip of Belzona® 4411 grip system was applied to the leading edge of the steps to create a non-slip surface.

BELZONA FACTS

The Belzona repairs improved the entrance to the town hall both in its appearance and the safety for its users.

INDUSTRY

General Industry

LOCATION

Town hall, France

APPLICATION DATE

February 2006

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 4411 (Granogrip)

SUBSTRATE

Tiles

PHOTOS

1. Close view of the damaged steps
2. Side view of the steps
3. Steps rebuilt with Belzona 4111
4. Completed application with Belzona 4411 grip system applied to leading edges

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

